



KCIA AIRPORT ADVISORY


DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.



GEOTECHNICAL INVESTIGATION & SURVEY MAY 10 (SATURDAY) - NORTH 4800 FEET CLOSURE MAP

Updated: 05/10/2003 at 16:30

1. **CLOSED** taxiway intersections: A4, B2 and B3.
2. A1/B1 taxiway intersections will remain open (taxiway signs connected to taxiway system not runway lighting system).
3. North 4800' feet closed of Runway 13R/31L.
4. Aircraft are to takeoff from temporary threshold marking/lighting only. No back taxi or early high speed taxi.
5. ABX has a scheduled departure at 23:45. If contractors are not finished at that time, they will clear for the departure and resume work until finished.
6. At this time, no partial closure will be needed tomorrow.

Distributed to: ARFF, ATCT, Maintenance, Engineering

Contact: Jamie Runyan Pager 206.986.9008 Cell 206.369.2716

KCSllp4 34420

SEA400967

ERROR INFORMATION

[*06]9p7633964
[*09]8p947395p6142381807
[*071]8p947395p5098840534
[*072]9p7637761
[*073]9p2533952458
[*074]9p6551454
[*005]9p7318558
[*013]9p7670755
[*014]9p2535291081
[*021]9p7632590
[*025]9p7689700
[*054]9p7644001
[*063]9p7637124
[*068]9p4252265314
[*075]9p6762645

MENTE AVAITION
AIRNET
EXECUTIVE FLIGHT
OTTER CORP
AIRBORNE EXPRESS
BOEING
AIRLIFT NW
AVOLO
B&B AIRCRAFT
FEDEX
GUIDO PERLA & AS
WA AERO
AMERICAN FLYERS
FBL JET
NATIONAL CHARTER

**KCIA AIRPORT ADVISORY**

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.


 *** MULTI TX/RX REPORT ***

TX/RX NO	3176	
PGS.	1	
TX/RX INCOMPLETE	[*017]9p7675440	BFI AVIATION
	[*024]9p4333619	GENISIS AIRCRAFT
	[*036]9p7681715	NORDSTROM
	[*038]9p7672549	NW EXEC AIR
	[*040]9p7638421	RAYTHEON AIRCRAF
	[*046]9p7860483	TC AVIATION
	[*053]9p7671600	WA AIR NATL GRD
	[*067]9p6220837	ROLING FLIGHT
	[*070]9p6550667P	DEPT OF DEFENSE
TRANSACTION OK	[*003]9p7621223	AIR TRANSPORT
	[*004]9p7630381	AIRBORNE EXPRESS
	[*006]9p7626357	AIRPAC AIRLINES
	[*007]9p7632036	AMERICAN AVIONIC
	[*008]9p7636239	AMERIFLIGHT
	[*009]9p7621158	AVIATION PARTNER
	[*010]9p7633428	AVIATION BOOK CO
	[*011]9p7647112	AVIATION TRAINIG
	[*012]9p7633428	AVIATOR STORE
	[*015]9p7620611	BAX GLOBAL
	[*016]9p6555116	BOEING CO
	[*018]9p7648124	CALIBER INSPECT
	[*019]9p7674018	CLASSIC HELICOPT
	[*022]9p7680888	FLIGHTCENTER
	[*023]9p7679333	GALVIN FLYING
	[*026]9p7689458	HELIJET
	[*027]9p7679333	KING BROADCASTIN
	[*028]9p7641904	KC JETCENTER
	[*029]63838	EMERGENCY MGMNT
	[*030]60514	SAFETY & CLAIMS
	[*031]64271	GUARDIAN ONE
	[*032]64271	SPECIAL OPS
	[*033]9p7626046	LINDEAN AIRCRAFT
	[*035]9p7641312	NATIONAL AVIATIO
	[*037]8p120329p6042782608	N VANCOUVER AIR
	[*039]9p7634837	PISTOL CREEK FIN
	[*043]9p7623542	SEATTLE JET STRM
	[*044]9p7633320	SERVICE GROUP
	[*045]9p7630381	SOUND AERIAL SVY
	[*047]9p7641986	TAG AVIATION
	[*048]9p7674920	UPS
	[*049]9p5536851	US CUSTOMS
	[*050]9p5530190	US IMMIGRATION
	[*051]9p7643862	VALKERIE CORP
	[*052]9p7644760	WA AUDIOLOGY
	[*055]9p7681947	WEST ISLE AIR
	[*056]9p7674539	WESTERN METALS
	[*057]9p7679464	WINGSALOFT
	[*058]9p7645707	MUS OF FLIGHT
	[*059]8p120329p6042735301	HELIJET
	[*060]8p120329p3602930517	WEST ISLE AIR
	[*061]9p7630381	AIR TRANSPORT
	[*062]9p7635156	S SEATTLE CC
	[*064]9p7622997	DUNCAN AVIONICS
	[*065]9p7677662	GALVIN-MAIT BLDG

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3175 92066586412
 CONNECTION TEL
 SUBADDRESS
 CONNECTION ID
 ST. TIME 05/10 16:21
 USAGE T 01'37
 PGS. SENT 1
 RESULT OK



GEOTECHNICAL INVESTIGATION & SURVEY MAY 10 (SATURDAY) - NORTH 4800 FEET CLOSURE

Updated: 05/10/2003 at 16:30

1. **CLOSED** taxiway intersections: A4, B2 and B3.
2. A1/B1 taxiway intersections will remain open (taxiway signs connected to taxiway system not runway light)
3. North 4800' feet closed of Runway 13R/31L.
4. Aircraft are to takeoff from temporary threshold marking/lighting only. No back taxi or early high speed taxi
5. ABX has a scheduled departure at 23:45. If contractors are not finished at that time, they will clear for the
6. At this time, no partial closure will be needed tomorrow.


Distributed to: ARFF, ATCT, Maintenance, Engineering

Cont

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO	3174	55055
CONNECTION TEL		
SUBADDRESS		
CONNECTION ID		
ST. TIME	POLICE	
USAGE T	05/10 16:17	
PGS. SENT	03'19	
RESULT	1	
	OK	



GEOTECHNICAL INVESTIGATION & SURVEY MAY 10 (SATURDAY) - NORTH 4800 FEET CLOSURE

Updated: 05/10/2003 at 16:30

1. **CLOSED** taxiway intersections: A4, B2 and B3.
2. A1/B1 taxiway intersections will remain open (taxiway signs connected to taxiway system not runway lig
3. North 4800' feet closed of Runway 13R/31L.
4. Aircraft are to takeoff from temporary threshold marking/lighting only. No back taxi or early high speed t
5. ABX has a scheduled departure at 23:45. If contractors are not finished at that time, they will clear for th
6. At this time, no partial closure will be needed tomorrow.

Distributed to: ARFF, ATCT, Maintenance, Engineering

Con

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO	3173	67385
CONNECTION TEL		
SUBADDRESS		
CONNECTION ID		
ST. TIME	05/10 16:08	
USAGE T	08'17	
PGS. SENT	1	
RESULT	OK	


MAINTENANCE

05/10 16:08

08'17

1

OK



GEOTECHNICAL INVESTIGATION & SURVEY MAY 10 (SATURDAY) - NORTH 4800 FEET CLOSURE

Updated: 05/10/2003 at 16:30

1. **CLOSED** taxiway intersections: A4, B2 and B3.
2. A1/B1 taxiway intersections will remain open (taxiway signs connected to taxiway system not runway light)
3. North 4800' feet closed of Runway 13R/31L.
4. Aircraft are to takeoff from temporary threshold marking/lighting only. No back taxi or early high speed taxi.
5. ABX has a scheduled departure at 23:45. If contractors are not finished at that time, they will clear for the
6. At this time, no partial closure will be needed tomorrow.

Distributed to: ARFF, ATCT, Maintenance, Engineering

Cont

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO	3170	55055
CONNECTION TEL		
SUBADDRESS		
CONNECTION ID		
ST. TIME	POLICE	
USAGE T	05/10 14:22	
PGS. SENT	03'15	
RESULT	1	
	OK	



**GEOTECHNICAL INVESTIGATION & SURVEY
 MAY 10 (SATURDAY) - NORTH 5000 FEET CLOSURE**

Updated: 05/10/2003 at 1454

1. **CLOSED** taxiway intersections: A4, A7, B4, B3, and B2.
2. B1/A1 will remain **open during daylight hours** for aircraft crossing.
3. North 5000' feet closed of Runway 13R/31L.
4. Aircraft are to takeoff from temporary threshold markings only. No back taxi or early high speed taxi to the

Distributed to: ARFF, ATCT, Maintenance, Engineering

Contact

KCSlip4 34426

SEA400973

 *** TX REPORT ***

TRANSMISSION OK

TX/RX NO

3171

CONNECTION TEL

67385

SUBADDRESS

CONNECTION ID

ST. TIME

MAINTENANCE
05/10 14:11

USAGE T


08 24

PGS. SENT

1

RESULT

OK



GEOTECHNICAL INVESTIGATION & SURVEY Y 10 (SATURDAY) - NORTH 5000 FEET CLOSURE MAP

Updated: 05/10/2003 at 1454

\7, B4, B3, and B2.

ght hours for aircraft crossing.

R/31L.

threshold markings only. No back taxi or early high speed taxi to the temporary relocated threshold.

Contact: Jamie Runyan Pager 206.986.9008 Cell 206.369.2716

KCSltp4 34427

SEA400974

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3180
CONNECTION TEL 97671550
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 08:32
USAGE T 01'13
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

A handwritten signature in cursive script, appearing to read "Runyan".

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3178
CONNECTION TEL 95211865
SUBADDRESS
CONNECTION ID AIRLIFT NORTHWES
ST. TIME 05/12 08:45
USAGE T 01'38
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3182
CONNECTION TEL 97625732
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 08:40
USAGE T 04'30
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3183
CONNECTION TEL 97674047
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 08:47
USAGE T 02:47
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003
TO: King County International Airport Tenants
distributed by fax
FROM: Jamie Runyan, Operations & Compliance Officer
SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO	3184	
CONNECTION TEL		97625481
SUBADDRESS		
CONNECTION ID		
ST. TIME	05/12 08:50	
USAGE T	02'46	
PGS. SENT	2	
RESULT	OK	

**KCIA AIRPORT ADVISORY****DATE:** May 10, 2003**TO:** King County International Airport Tenants
distributed by fax**FROM:** Jamie Runyan, Operations & Compliance Officer**SUBJECT: Sunday (May 11) Construction Schedule Revised**

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

A handwritten signature in cursive script, appearing to read "Runyan".

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3185
CONNECTION TEL 97640142
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 08:53
USAGE T 05'03
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3186
CONNECTION TEL 97675604
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 08:59
USAGE T 05'45
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3187
CONNECTION TEL 94253937741
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 09:05
USAGE T 01'54
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3188
CONNECTION TEL 97671726
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 09:07
USAGE T 13'30
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3189
CONNECTION TEL 97673367
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 09:21
USAGE T 02'21
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003
TO: King County International Airport Tenants
distributed by fax
FROM: Jamie Runyan, Operations & Compliance Officer
SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO 3181
CONNECTION TEL 97621561
SUBADDRESS
CONNECTION ID
ST. TIME 05/12 08:33
USAGE T 05'44
PGS. SENT 2
RESULT OK



KCIA AIRPORT ADVISORY

DATE: May 10, 2003
TO: King County International Airport Tenants
distributed by fax
FROM: Jamie Runyan, Operations & Compliance Officer
SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

*** TX REPORT ***

TRANSMISSION OK

TX/RX NO	3192	
CONNECTION TEL		97680483
SUBADDRESS		
CONNECTION ID		
ST. TIME	05/12 10:10	
USAGE T	10'47	
PGS. SENT	2	
RESULT	OK	



KCIA AIRPORT ADVISORY

DATE: May 10, 2003

TO: King County International Airport Tenants
distributed by fax

FROM: Jamie Runyan, Operations & Compliance Officer

SUBJECT: Sunday (May 11) Construction Schedule Revised

The geotechnical investigation and survey conducted today (Saturday) on Runway 13R/31L went faster than anticipated; therefore, please check NOTAMs at approximately 23:00 (Saturday night) for changes to Sunday's restrictions. If work continues at the current completion rate, no restrictions or partial closures will be needed on Sunday, but this can not be guaranteed at this time. Again, CHECK NOTAMs.

A handwritten signature in cursive script, appearing to read "Runyan".